




Base Materials for Strainers




1/16" Ø on 1/8" ctrs.



1/8" Ø on 3/16" ctrs.



3/16" Ø on 1/4" ctrs.



1/4" Ø on 3/8" ctrs.

Perforated Materials

Gage	Perforation	Holes/sq. in.	% of Open Area	Material Range
20	1/16" Ø on 1/8" ctrs.	74.0	22.7%	Carbon Steel, 304SS, 316SS
16	1/8" Ø on 3/16" ctrs.	33.0	40.3%	Carbon Steel, 304SS, 316SS 304L, 316L, Monel
16	3/16" Ø on 1/4" ctrs.	18.5	51.0%	Carbon Steel, 304SS, 316SS
16	1/4" Ø on 3/8" ctrs.	8.0	40.3%	Carbon Steel, 304SS, 316SS
14	1/8" Ø on 3/16" ctrs.	33.0	40.3%	Carbon Steel, 304SS, 316SS
14	3/16" Ø on 1/4" ctrs.	18.5	51.0%	Carbon Steel, 304SS, 316SS
14	1/4" Ø on 3/8" ctrs.	8.0	40.3%	Carbon Steel, 304SS, 316SS
12	1/8" Ø on 3/16" ctrs.	33.0	40.3%	Carbon Steel
11	1/8" Ø on 3/16" ctrs.	33.0	40.3%	304SS, 316SS
11	1/4" Ø on 3/8" ctrs.	8.0	40.3%	Carbon Steel, 304SS, 316SS